National Transportation Safety Board NTSB ID: ANC98IA004 Aircraft Registration Number: N9304F FACTUAL REPORT Occurrence Date: 10/20/1997 Most Critical Injury: None AVIATION Occurrence Type: Incident Investigated By: NTSB Location/Time Nearest City/Place State Zip Code Local Time Time Zone 1000 KASIGLUK 99609 ADT ΑK Distance From Landing Facility: Direction From Airport: Airport Proximity: On Airport Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft Cessna 208B Airplane Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On October 20, 1997, about 1000 Alaska daylight time, a Cessna 208B airplane, N9304F, had a left aileron jam during the landing approach to the Kasigluk Airport, Kasigluk, Alaska. The airplane was being operated as a visual flight rules (VFR) nonscheduled cargo flight under Title 14 CFR Part 135 when the incident occurred. The airplane, operated by Peninsula Airways Inc., Anchorage, Alaska, was not damaged. The certificated airline transport pilot, the sole occupant, was not injured. Visual meteorological conditions prevailed. VFR company flight following procedures were in effect. The flight originated at the Bethel Airport, Bethel, Alaska, at 0930.

The pilot reported he was maneuvering to land on runway 35 at the Kasigluk Airport, and began a left turn to enter the downwind portion of the landing approach. During the turn, the pilot utilized full aileron deflection, and noticed the aileron momentarily jammed. He was able to force the control wheel to the right, unjamming the aileron. The pilot continued the landing approach, and landed without encountering further control problems.

The pilot indicated that following the landing, he began to taxi to the ramp. Due to a strong crosswind, the pilot deflected the ailerons fully to the left. The aileron once again jammed, and the pilot was unable to force the control wheel to the right. The operator reported the incident flight was the first flight of the day for the airplane.

The airplane ailerons utilize balance weights that are attached to the interior surface of the leading edge of the aileron at the inboard, and outboard ends of the aileron. Five screws are inserted through the leading edge skin of the aileron, through the balance weight, and into self-locking nuts attached to a nut strip assembly.

Company maintenance personnel conducted an inspection of the aileron, and reported 1 screw was missing. Three of the remaining 4 screws were loose, and backed out sufficient distance to contact the trailing edge of the wing, forward of the aileron. The left aileron was jammed in a full, leading edge down, position.

The operator's maintenance personnel replaced the screws, and did not report any obvious failure or damage to the attaching screws. The operator found slightly loose balance weight screws in other Cessna 208B airplanes. In each case, the self-locking nutplates still had proper grip. The operator indicated their maintenance department personnel have since applied loctite to each screw.

The Cessna 208B information manual provides a description of a preflight inspection that includes an examination of the ailerons as part of a walk-around inspection of the airplane. In addition, the balance weights should be inspected during every 100 hour inspection.

A review of the manufacturer's service condition report data base, and the Federal Aviation Administration malfunction and defect report system did not reveal any other reported incidents of

TRANSPO
National Transportation Safety Board
0 7
FACTUAL REPORT
7
AVIATION

NTSB ID: ANC98IA004

AVIATION	Occurrence Type: Incident	
Narrative (Continued)		
aileron jamming.		
	FACTUAL REPORT - AVIATION	Page 1a

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ANC98IA004

TACIDAL REFORT	0000		Date.	10/20/1997									
AVIATION Occurrence Type: Incident													
Landing Facility/Approach Information													
Airport Name	Airpor	rt ID:	Airport Eleva	tion	Run	way Used	Runwa	ay Length R		Runw	ay Width		
KASIGLUK		Z09		40 Ft.	MSL	35		5		50			
Runway Surface Type: Gravel													
Runway Surface Condition: Dry													
Type Instrument Approach: NONE													
VFR Approach/Landing: Full Stop													
Aircraft Information													
Aircraft Manufacturer Cessna			Model/ 208B	Series					Serial 2080	Number 0008	•		
Airworthiness Certificate(s): Normal													
Landing Gear Type: Tricycle													
Homebuilt Aircraft? No Number of	Seats: 9	c	Certified	d Max Gross W	/t.		8750	LBS	Numbe	nber of Engines: 1			
Engine Type: Turbo Prop					Engine Manufacturer: Model/Series: P&W PT6A-114							Rated Power: 600 HP	
- Aircraft Inspection Information													
Type of Last Inspection		Date	Date of Last Inspection Time Since Last Inspection							Airframe Total Time			
Continuous Airworthiness		09/2	09/25/1997 34 Hours							8638 Hours			
- Emergency Locator Transmitter (ELT) Informa	ation												
ELT Installed? Yes ELT	Operated? No	0			ELT.	Aided i	n Locating Acc	cident S	ite?				
Owner/Operator Information													
Registered Aircraft Owner		s	Street A	ddress 2404 ME	RRILL	_ FIEL	D DR.						
AVION CAPITAL CORP.	С	City State Zip 0							Zip Code 99501				
Street Address													
Operator of Aircraft 6100 BOEING AVE.													
PENINSULA AIRWAYS INC.	Ci	City State Zip Code ANCHORAGE AK 99516											
Operator Does Business As:			O	perator Desigr	nator Co	de: PN	SA						
- Type of U.S. Certificate(s) Held:													
Air Carrier Operating Certificate(s): Commuted	Air Carrier;	Flag C	Carrier	/Domestic; O	n-dem	and A	ir Taxi						
Operating Certificate:				Operator C	Certifica	ate:							
Regulation Flight Conducted Under: Part 135: Air Taxi & Commuter													
Type of Flight Operation Conducted: Unknown	1												
	FACT	UAL I	REPO:	RT - AVIATI	ON							Page 2	

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ANC98IA004

AVIATION Occurrence Type: Incident						ident							
First Pilot Information													
Name City										S	tate	Date of Birth	Age
On File On F							!			35			
Sex: M	n Pilot				Certific	ate Num	ber: On File	•					
Sex: M Seat Occupied: Unknown Principal Profession: Civilian Pilot Certificate Number: On File Certificate(s): Airline Transport; Commercial													
Airplane Rating(s): Multi-engine Land; Single-engine Land													
Rotorcraft/Glider/LTA: None													
Instrument	Rating(s): Airpl	ane											
Instructor F	ating(s): None	Э											
Type Rating/Endorsement for Accident/Incident Aircraft? Current Biennial Flight Review?													
Medical Ce	rt.: Class 1	Medica	al Cert. Status	s: Valid Med	dicalno wa	aivers/lin	n.		Date	of Last I	Medical I	Exam: 08/30/1	997
		I											
- Flight Tim	e Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night		Ins Actual	Instrument al Simulated		Rotorcraft	Glider	Lighter Than Air
Total Time		5800	150	4700	1100	,	150	18	180				
Pilot In Cor	nmand(PIC)	5500	150	4500	1000		150	18)				
Instructor													
Last 90 Day	/S	180											
Last 30 Day		60					_						
Last 24 Ho		5				 					<u> </u>		
Seatbelt Us	sed? Yes	Shou	lder Harness	Used? Yes		Т	oxico	logy Perfo	rmed?	No		Second Pilot? N	10
Flight Pla	n/Itinerary												
		ompany VFI	 R										
Type of Flight Plan Filed: Company VFR Departure Point								Air	port Ide	ntifier	Departure Time		Time Zone
BETHEL									BET		0930		ADT
Destination State Airport Identifier													
Same as Accident/Incident Location Z09													
Type of Cle	arance: None												
Type of Air	space: Class	G											
Weather	Information												
Source of I		ord of briefi	ng										
Method of	Briefing:												
				FACTUAL	REPORT -	- AVIA	ΓΙΟΝ	1					Page 3

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ANC98IA004

	AVIATION			Occurrence Type: Incident								
Weather Information												
WOF ID	Observation Time	Time Zon	e V	WOF Elevat	ion	WOF Di	istance Fro	om Acci	dent Site		Direction From Acc	ident Site
	0000			0 Ft	. MSL				0 NM			0 Deg. Mag.
Sky/Lowes	st Cloud Condition: Cle	ear					0 Ft. A	\GL	Condition o	of Ligh	nt: Day	
Lowest Ce	iling: None			0 Ft.	AGL	Visibi	ility:	20	SM	"Hg		
Temperatu	ure: -12 °C	Dew Point:		°C	Wind	Direction:	315			Der	nsity Altitude:	Ft.
Wind Spee	ed: 25	Gusts:	35		Weat	her Condt	ions at Acc	cident S	ite: Visual C	Condi	itions	
Visibility (R	RVR): 0 F	t. Visibili	ity (RVV)	′) 0	SM	Intensity	y of Precip	oitation:	Unknown			
Restriction	ns to Visibility: None											
Type of Pre	Type of Precipitation: None											
Accident	Information											
Aircraft Dar	mage:			Aircraft Fir	e:				Aircraft Exp	losior	n	
Classificati	on:											
- Injury Sur	mmary Matrix	Fatal	Seriou	us Mino	or	None TOTAL						
First Pi	llot					1		1				
Second	d Pilot											
Studen	nt Pilot	1						7				
Flight I	nstructor							7				
Check	Pilot							7				
Flight E	Engineer							\neg				
Cabin /	Attendants							7				
Other C	Crew	1						7				
Passen	ngers		†					7				
- TOTAL F	ABOARD -					1		1				
Other G	Ground	0		0	0			0				
- GRAND	O TOTAL -	0		0	0	1		1				

National Transportation Safety Board
FACTUAL REPORT

NTSB ID: ANC98IA004

Occurrence Date: 10/20/1997

Occurrence Type: Incident

Administrative	

Investigator-In-Charge (IIC)

SCOTT R. ERICKSON

Additional Persons Participating in This Accident/Incident Investigation:

TOM ELDRIDGE FAA-AL-ANC-FSDO ANCHORAGE, AK 99502